US Tech Test Report:
 FCC Part 15 Certification

 FCC ID:
 2ABP2-EST0117

 IC:
 11753A-EST0217

 Test Report Number:
 17-0142

 Issue Date:
 June 21, 2017

 Customer:
 Estimote

 Model:
 Beacon G1.12

TEST CONFIGURATION PHOTOGRAPHS



Figure 1. Intentional Radiated Emissions Test Setup (Worst Case Position)



Figure 2. Intentional Radiated Emissions Test Setup, Above 1GHz



Figure 3. Radiated Emissions Test Setup, Below 30 MHz (X-Position)



Figure 4. Radiated Emissions Test Setup, Below 30 MHz (Y-Position)

 US Tech Test Report:
 FCC Part 15 Certification

 FCC ID:
 2ABP2-EST0117

 IC:
 11753A-EST0217

 Test Report Number:
 17-0142

 Issue Date:
 June 21, 2017

 Customer:
 Estimote

 Model:
 Beacon G1.12




Figure 5. Radiated Emissions Test Setup, Below 30 MHz (Z-Position)

 US Tech Test Report:
 FCC Part 15 Certification

 FCC ID:
 2ABP2-EST0117

 IC:
 11753A-EST0217

 Test Report Number:
 17-0142

 Issue Date:
 June 21, 2017

 Customer:
 Estimote

 Model:
 Beacon G1.12



Figure 6. Radiated Emissions Test Setup, 30 MHz to 200 MHz (For Both Intentional and Unintentional Emissions)




Figure 7. Radiated Emissions Test Setup, 200 MHz to 1000 MHz (For Both Intentional and Unintentional Emissions)



Figure 8. Unintentional Radiated Emissions Test Above 1 GHz



Figure 9. Unintentional Radiated Emission Test Setup, Front