US Tech Test Report: FCC ID: Test Report Number: Issue Date: Customer: Model: FCC Part 15 Certification 2ABP2-EST0216 16-0265 November 18, 2016 Estimote Polska Sp. z. o. o. Beacon H1.7

INTERNAL PHOTOGRAPHS



Figure 1. Component Side of PCB

US Tech Test Report: FCC ID: Test Report Number: Issue Date: Customer: Model: FCC Part 15 Certification 2ABP2-EST0216 16-0265 November 18, 2016 Estimote Polska Sp. z. o. o. Beacon H1.7




Figure 2. Close-up of RF Circuit

US Tech Test Report: FCC ID: Test Report Number: Issue Date: Customer: Model:

FCC Part 15 Certification 2ABP2-EST0216 16-0265 November 18, 2016 Estimote Polska Sp. z. o. o. Beacon H1.7



Figure 3. Solder Side of PCB