


# Appendix A. Setup Photographs

# <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABQW-BPH Page Number : A1 of A2
Report Issued Date : Apr. 02, 2014
Report Version : Rev. 01

Report No.: FR421348D

Report Template No.: BU5-FR15EWL Version 1.0




# Report No.: FR421348D


## <Radiated Emission>

### X Plane

LF



### HF



### SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABQW-BPH Page Number : A2 of A2 Report Issued Date: Apr. 02, 2014 Report Version : Rev. 01

Report Template No.: BU5-FR15EWL Version 1.0