

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABQW-BPH Page Number : A1 of A2
Report Issued Date : Apr. 02, 2014
Report Version : Rev. 01

Report No.: FR421348A

Report Template No.: BU5-FR15CBT Version 1.0




Test Report No. : FR421348A


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABQW-BPH Page Number : A2 of A2
Report Issued Date : Apr. 02, 2014
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.0