

# Appendix A. Setup Photographs

## <Conducted Emission>

### Mode 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABQW-BPH Page Number : A1 of A3
Report Issued Date : Apr. 02, 2014
Report Version : Rev. 01

Report No.: FR421348C


Report Template No.: BU5-FR15CWL Version 1.0




## <Radiated Emission>

## X Plane for 2.4GHz

LF



HF



### SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABQW-BPH Page Number : A2 of A3
Report Issued Date : Apr. 02, 2014
Report Version : Rev. 01


Report No.: FR421348C

Report Template No.: BU5-FR15CWL Version 1.0




Y Plane for 5GHz

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABQW-BPH Page Number : A3 of A3
Report Issued Date : Apr. 02, 2014
Report Version : Rev. 01

Report No.: FR421348C

Report Template No.: BU5-FR15CWL Version 1.0