Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01



1 Photographs of Conducted Emissions Test Configuration




FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01






SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01




2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



: A4 of A5


: Rev. 01

REAR VIEW


SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version



For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5
Report Version : Rev. 01