

132431_k.JPG: CRA61, internal view 1

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E1

 Date of issue:
 17 February 2014
 Order No.:
 13-111991 and 13-111992
 page 1 of 6






132431_I.JPG: CRA61, internal view 2

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E1

 Date of issue:
 17 February 2014
 Order No.:
 13-111991 and 13-111992
 page 2 of 6






132431_q.JPG: CRA61, main PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E1

 Date of issue:
 17 February 2014
 Order No.:
 13-111991 and 13-111992
 page 3 of 6






132431_r.JPG: CRA61, main PCB, bottom view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E1

 Date of issue:
 17 February 2014
 Order No.:
 13-111991 and 13-111992
 page 4 of 6






132431_m.JPG: CRA61, Antenna PCB, top view

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E1

 Date of issue:
 17 February 2014
 Order No.:
 13-111991 and 13-111992
 page 5 of 6





132431_n.JPG: detail view to RF-module, cover removed

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E1

 Date of issue:
 17 February 2014
 Order No.:
 13-111991 and 13-111992
 page 6 of 6