

132431_29.JPG: CRA61, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E3

 Date of issue:
 17 February 2014
 Order No.:
 13-112431
 page 1 of 6






132431_32.JPG: CRA61, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E3

 Date of issue:
 17 February 2014
 Order No.:
 13-112431
 page 2 of 6






132431_31.JPG: CRA61, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E3

 Date of issue:
 17 February 2014
 Order No.:
 13-112431
 page 3 of 6





132431_30.JPG: CRA61, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E3

 Date of issue:
 17 February 2014
 Order No.:
 13-112431
 page 4 of 6






132431_27.JPG: CRA61, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E3

 Date of issue:
 17 February 2014
 Order No.:
 13-112431
 page 5 of 6





132431_34.JPG: CRA61, test set-up open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F132431E3

 Date of issue:
 17 February 2014
 Order No.:
 13-112431
 page 6 of 6