


TEL: 886-3-327-3456 Page Number : C140 of C148




TEL: 886-3-327-3456 Page Number : C141 of C148


2.4GHz 2400~2483.5MHz

Report No.: FR860615C


WIFI 802.11n HT20 (Harmonic @ 3m)



TEL: 886-3-327-3456 Page Number : C142 of C148



TEL: 886-3-327-3456 Page Number : C143 of C148




TEL: 886-3-327-3456 Page Number : C144 of C148


2.4GHz 2400~2483.5MHz

Report No.: FR860615C

WIFI 802.11n HT40 (Harmonic @ 3m)



TEL: 886-3-327-3456 Page Number : C145 of C148




TEL: 886-3-327-3456 Page Number : C146 of C148



TEL: 886-3-327-3456 Page Number : C147 of C148

Emission below 1GHz

Report No.: FR860615C



TEL: 886-3-327-3456 Page Number : C148 of C148





Appendix D. Duty Cycle Plots

Antenna	Band	Duty Cycle(%)	T(us)	1/T(kHz)	VBW Setting	Duty Factor(dB)
1	802.11b	98.56	-	-	10Hz	0.06
2	802.11b	98.56		-	10Hz	0.06
1+2	802.11b for Ant. 1	99.03	-	-	10Hz	0.04
1+2	802.11b for Ant. 2	98.56	-	-	10Hz	0.06
1	802.11g	97.14	2040.00	0.49	1kHz	0.13
2	802.11g	97.14	2040.00	0.49	1kHz	0.13
1+2	802.11g for Ant. 1	97.14	2040.00	0.49	1kHz	0.13
1+2	802.11g for Ant. 2	97.14	2040.00	0.49	1kHz	0.13
1	2.4GHz 802.11n HT20	97.94	1900.00	0.53	1kHz	0.09
2	2.4GHz 802.11n HT20	97.94	1900.00	0.53	1kHz	0.09
1+2	2.4GHz 802.11n HT20 for Ant. 1	97.94	1900.00	0.53	1kHz	0.09
1+2	2.4GHz 802.11n HT20 for Ant. 2	96.92	1890.00	0.53	1kHz	0.14
1	2.4GHz 802.11n HT40	96.91	940.00	1.06	3kHz	0.14
2	2.4GHz 802.11n HT40	95.92	940.00	1.06	3kHz	0.18
1+2	2.4GHz 802.11n HT40 for Ant. 1	95.92	940.00	1.06	3kHz	0.18
1+2	2.4GHz 802.11n HT40 for Ant. 2	95.92	940.00	1.06	3kHz	0.18


Report No.: FR860615C

TEL: 886-3-327-3456 Page Number : D1 of D9




Report No.: FR860615C





Date: 13.JUN.2018 16:43:32


802.11g



Date: 13.JUN.2018 16:52:03


TEL: 886-3-327-3456 Page Number : D2 of D9





Date: 13.JUN.2018 16:50:57

802.11n HT40




Date: 13.JUN.2018 16:58:06

TEL: 886-3-327-3456 Page Number : D3 of D9




Report No.: FR860615C





Date: 13.JUN.2018 16:43:32

802.11g




Date: 13.JUN.2018 16:48:45

FAX: 886-3-328-4978


TEL: 886-3-327-3456 Page Number : D4 of D9





Date: 13.JUN.2018 16:49:57

802.11n HT40




Date: 13.JUN.2018 16:58:58

TEL: 886-3-327-3456 Page Number : D5 of D9


MIMO <Ant. 1>

802.11b



Date: 13.JUN.2018 16:42:56

802.11g




Date: 13.JUN.2018 17:08:14

TEL: 886-3-327-3456 Page Number : D6 of D9


Report No.: FR860615C





Date: 13.JUN.2018 16:53:11

802.11n HT40




Date: 13.JUN.2018 16:56:39

TEL: 886-3-327-3456 Page Number : D7 of D9


MIMO <Ant. 2>

802.11b



Date: 13.JUN.2018 16:43:32

802.11g




Date: 13.JUN.2018 17:07:28

TEL: 886-3-327-3456 Page Number : D8 of D9




Report No.: FR860615C





Date: 13.JUN.2018 16:53:59

802.11n HT40



Date: 13.JUN.2018 16:57:19

TEL: 886-3-327-3456 Page Number : D9 of D9