
Appendix A. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3SC-1 Page Number : A1 of A2
Report Issued Date : Sep. 19, 2014
Report Version : Rev. 01

Report No. : FR442473

Report Template No.: BU5-FR15CBT Version 1.0


Report No.: FR442473

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3SC-1 Page Number : A2 of A2
Report Issued Date : Sep. 19, 2014
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.0