



Report No. : EP952848




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 5 of 10
EP Report Version : Rev. 01
Issued Date : Jun. 20, 2019








SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 6 of 10
EP Report Version : Rev. 01
Issued Date : Jun. 20, 2019

Report No.: EP952848






Report No.: EP952848




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 7 of 10
EP Report Version : Rev. 01
Issued Date : Jun. 20, 2019






Report No.: EP952848




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 8 of 10
EP Report Version : Rev. 01
Issued Date : Jun. 20, 2019







SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 9 of 10

EP Report Version : Rev. 01


Issued Date : Jun. 20, 2019

Report No.: EP952848





Report No.: EP952848



——THE END—

SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 10 of 10 EP Report Version : Rev. 01 Issued Date : Jun. 20, 2019