Test report No. : 11740660H-A-R1
Page : 30 of 31
Issued date : January 19, 2018
FCC ID : 2ABXRMB3002WB

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Ise EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124


Test report No. : 11740660H-A-R1
Page : 31 of 31
Issued date : January 19, 2018
FCC ID : 2ABXRMB3002WB

Worst Case Position (Horizontal: X-axis/ Vertical: X-axis)


X-axis



Y-axis



Z-axis



End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124