




BAT VCC_CRI616_2 CRI616_SMD D1 VCC_BAT VCC_CRI616_1 BATS4C VCC_CRI616_1 BATS4C VCC_RI616_SMD


BUZZER





MEM





































IC_CARD



















Net_Name		
Value	USB_EN	
Н	external power is off	inhibition
Floating	inhibition	inhibition
L	USB	

refer to LCD module:resistor inside


Net_Name Value	LCD_RST, /LCD_CS	
HH	Reserved	
LH	Reserved	
LH	Reserved	
LL	ST7567	V





Net_Name	100 051 01/ 51/ 100 0	
$\overline{}$	ICC_SEL3V_5V, ICC_S	ELT.8V
HH	NC	
floating	no IC,no SAM	
LH	IC configuration, but no SAM	
LL	TDA8035	1





Net Name		
Value	AUDIO_CAP1	
Н	No Audio	
Following	Audio	











SCR_IC>>03: IC/SAM_CARD

