Client	Interaxon Inc	
Product	MUSE, Model: MU-02	GLOBAL
Standard(s)	RSS 247 Issue 1/ FCC Part 15 Subpart C 15:2015	EMC'INC

Internal photos



Figure 1: Internal view – left PCB top view

Page 1 of 6 Report issue date: 12/8/2015 GEMC File #: GEMC-FCC-22967R0

Client	Interaxon Inc	
Product	MUSE, Model: MU-02	GLOBAL
Standard(s)	RSS 247 Issue 1/ FCC Part 15 Subpart C 15:2015	EMC'INC




Figure 2: Internal view – left PCB, rear view

Page 2 of 6 Report issue date: 12/8/2015 GEMC File #: GEMC-FCC-22967R0

Client	Interaxon Inc	
Product	MUSE, Model: MU-02	GLOBAL
Standard(s)	RSS 247 Issue 1/ FCC Part 15 Subpart C 15:2015	EMCINC



Figure 3: Internal view, right PCB top view 1

Page 3 of 6 Report issue date: 12/8/2015 GEMC File #: GEMC-FCC-22967R0

Client	Interaxon Inc	
Product	MUSE, Model: MU-02	GLOBAL
Standard(s)	RSS 247 Issue 1/ FCC Part 15 Subpart C 15:2015	EMC'INC




Figure 4: Internal view, right PCB top view 2

Page 4 of 6 Report issue date: 12/8/2015 GEMC File #: GEMC-FCC-22967R0

Client	Interaxon Inc	
Product	MUSE, Model: MU-02	GLOBAL
Standard(s)	RSS 247 Issue 1/ FCC Part 15 Subpart C 15:2015	EMC'INC




Figure 5: Internal photo – right PCB rear view

Page 5 of 6 Report issue date: 12/8/2015 GEMC File #: GEMC-FCC-22967R0

Client	Interaxon Inc	
Product	MUSE, Model: MU-02	GLOBAL
Standard(s)	RSS 247 Issue 1/ FCC Part 15 Subpart C 15:2015	EMC'INC



Figure 6: Internal photo – right PCB rear view with RF shield removed

Page 6 of 6 Report issue date: 12/8/2015 GEMC File #: GEMC-FCC-22967R0