




Band7 / 15MHz / Low CH / QPSK




Band7 / 15MHz / Low CH / 16QAM




Band7 / 15MHz / Mid CH / QPSK




Band7 / 15MHz / Mid CH / 16QAM



Band7 / 15MHz / High CH / QPSK




Band7 / 15MHz / High CH / 16QAM






Band7 / 20MHz / Low CH / QPSK



Band7 / 20MHz / Low CH / 16QAM



Band7 / 20MHz / Mid CH / QPSK



Band7 / 20MHz / Mid CH / 16QAM



Band7 / 20MHz / High CH / QPSK




Band7 / 20MHz / High CH / 16QAM






Band38 / 5MHz / Low CH / QPSK



Band38 / 5MHz / Low CH / 16QAM




Band38 / 5MHz / Mid CH / QPSK




Band38 / 5MHz / Mid CH / 16QAM



Band38 / 5MHz / High CH / QPSK



Band38 / 5MHz / High CH / 16QAM







Band38 / 10MHz / Low CH / QPSK




Band38 / 10MHz / Low CH / 16QAM




Band38 / 10MHz / Mid CH / QPSK



Band38 / 10MHz / Mid CH / 16QAM



Band38 / 10MHz / High CH / QPSK




Band38 / 10MHz / High CH / 16QAM







Band38 / 15MHz / Low CH / QPSK




Band38 / 15MHz / Low CH / 16QAM




Band38 / 15MHz / Mid CH / QPSK




Band38 / 15MHz / Mid CH / 16QAM



Band38 / 15MHz / High CH / QPSK




Band38 / 15MHz / High CH / 16QAM







Band38 / 20MHz / Low CH / QPSK




Band38 / 20MHz / Low CH / 16QAM




Band38 / 20MHz / Mid CH / QPSK




Band38 / 20MHz / Mid CH / 16QAM




Band38 / 20MHz / High CH / QPSK



Band38 / 20MHz / High CH / 16QAM









REPORT No. : SZ19120009W03

Band40 / 10MHz / Mid CH / QPSK



Band40 / 10MHz / Mid CH / 16QAM




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555
Fax: 86-755-36698525
[Http://www.morlab.cn](http://www.morlab.cn)
E-mail: service@morlab.cn



REPORT No. : SZ19120009W03

**MORLAB**


SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No. : SZ19120009W03

Band40 / 10MHz / Mid CH / QPSK



Band40 / 10MHz / Mid CH / 16QAM






Band41 / 5MHz / Low CH / QPSK




Band41 / 5MHz / Low CH / 16QAM




Band41 / 5MHz / Mid CH / QPSK



Band41 / 5MHz / Mid CH / 16QAM



Band41 / 5MHz / High CH / QPSK




Band41 / 5MHz / High CH / 16QAM







Band41 / 10MHz / Low CH / QPSK




Band41 / 10MHz / Low CH / 16QAM



Band41 / 10MHz / Mid CH / QPSK



Band41 / 10MHz / Mid CH / 16QAM



Band41 / 10MHz / High CH / QPSK



Band41 / 10MHz / High CH / 16QAM

