



REPORT No.: SZ18050200W08

LTE Band 4 10MHz BW Low Channel QPSK



16QAM



MORLAB


SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No.: SZ18050200W08

LTE Band 4 10MHz BW Mid Channel QPSK




16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China


Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn





REPORT No.: SZ18050200W08

LTE Band 4 15MHz BW Low Channel QPSK



16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No.: SZ18050200W08

LTE Band 4 15MHz BW Mid Channel QPSK




16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn






REPORT No.: SZ18050200W08

LTE Band 4 20MHz BW Low Channel QPSK



16QAM



MORLAB


SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn

LTE Band 4 20MHz BW Mid Channel QPSK




16QAM








LTE Band 7 5MHz BW Low Channel QPSK







LTE Band 7 5MHz BW High Channel
 QPSK




LTE Band 7 10MHz BW Mid Channel
 QPSK


16QAM







REPORT No.: SZ18050200W08

LTE Band 7 15MHz BW Low Channel QPSK




MORLAB


SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn






LTE Band 7 20MHz BW Low Channel QPSK





REPORT No.: SZ18050200W08

LTE Band 7 20MHz BW Mid Channel QPSK




MORLAB


SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn

LTE Band 7 20MHz BW High Channel QPSK









REPORT No.: SZ18050200W08

LTE Band 12 1.4MHz BW High Channel QPSK



16QAM




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn

LTE Band 12 3MHz BW Low Channel
 QPSK


16QAM



LTE Band 12 3MHz BW Mid Channel QPSK




16QAM





REPORT No.: SZ18050200W08

LTE Band 12 3MHz BW High Channel QPSK



16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn

LTE Band 12 5MHz BW Low Channel QPSK




16QAM



LTE Band 12 5MHz BW Mid Channel QPSK



16QAM





REPORT No.: SZ18050200W08

LTE Band 12 5MHz BW High Channel QPSK




16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China


Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn



LTE Band 12 10MHz BW Mid Channel
 QPSK



16QAM






LTE Band 17 5MHz BW Low Channel
 QPSK


16QAM



LTE Band 17 5MHz BW Mid Channel
 QPSK


16QAM





REPORT No.: SZ18050200W08

LTE Band 17 5MHz BW High Channel QPSK



16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn



REPORT No.: SZ18050200W08

LTE Band 17 10MHz BW Low Channel QPSK



16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn



REPORT No.: SZ18050200W08

LTE Band 17 10MHz BW Mid Channel QPSK




16QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn





2.6. Band Edge

2.6.1. Requirement


According to FCC section 24.238(a), The power of any emission outside of the authorized operating frequency ranges must be attenuated below the transmitting power (P) by a factor of at least $43 + 10 \log(P)$ dB.

According to FCC section 27.53(g), For operations in the 698–746 MHz band, the power of any emission outside a licensee's frequency band(s) of operation shall be attenuated below the transmitter power (P) within the licensed band(s) of operation, measured in watts, by at least $43 + 10 \log (P)$ dB. Compliance with this provision is based on the use of measurement instrumentation employing a resolution bandwidth of 100 kilohertz or greater. However, in the 100 kilohertz bands immediately outside and adjacent to a licensee's frequency block, a resolution bandwidth of at least 30 kHz may be employed.

According to FCC section 27.53(h), For operations in the 1710–1755MHz bands, the power of any emission outside a licensee's frequency block shall be attenuated below the transmitter power (P) by at least $43 + 10 \log_{10}(P)$ dB.

According to FCC section 27.53(m) (4), For mobile digital stations, the attenuation factor shall be not less than $40 + 10 \log (P)$ dB on all frequencies between the channel edge and 5 megahertz from the channel edge, $43 + 10 \log (P)$ dB on all frequencies between 5 megahertz and X megahertz from the channel edge, and $55 + 10 \log (P)$ dB on all frequencies more than X megahertz from the channel edge, where X is the greater of 6 megahertz or the actual emission bandwidth as defined in paragraph (m)(6) of this section. In addition, the attenuation factor shall not be less than $43 + 10 \log (P)$ dB on all frequencies between 2490.5 MHz and 2496 MHz and $55 + 10 \log (P)$ dB at or below 2490.5 MHz. Mobile Satellite Service licensees operating on frequencies below 2495 MHz may also submit a documented interference complaint against BRS licensees operating on channel BRS Channel 1 on the same terms and conditions as adjacent channel BRS or EBS licensees.

2.6.2. Test Description



The EUT is coupled to the Spectrum Analyzer (SA) and the System Simulator (SS) with Attenuators through the Power Splitter; the RF load attached to the EUT antenna terminal is 50Ohm; the path loss as the factor is calibrated to correct the reading. The EUT is commanded by the SS to operate at the maximum output power. A call is established between the EUT and the SS.

2.6.3. Test procedure

KDB 971168 D01v03 Section 6.0 and ANSI/TIA-603-E-2016.

2.6.4. Test Result

The center frequency of spectrum is the band edge frequency and span is 2MHz, Record the max trace into the test report.




REPORT No.: SZ18050200W08

LTE Band 2


Channel Bandwidth: 1.4MHz

Channel	18607	RB Size 1	RB Offset 0	Channel	18607	RB Size 6	RB Offset 0
---------	-------	-----------	-------------	---------	-------	-----------	-------------



Channel Bandwidth: 1.4MHz

Channel	19192	RB Size 1	RB Offset 5	Channel	19192	RB Size 6	RB Offset 0
---------	-------	-----------	-------------	---------	-------	-----------	-------------



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China


Tel: 86-755-36698555 Fax: 86-755-36698525
[Http://www.morlab.cn](http://www.morlab.cn) E-mail: service@morlab.cn




REPORT No.: SZ18050200W08

LTE Band 2

Channel Bandwidth: 3MHz



Channel Bandwidth: 3MHz




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China


Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn

LTE Band 2

Channel Bandwidth: 5MHz



Channel Bandwidth: 5MHz






REPORT No.: SZ18050200W08

LTE Band 2


Channel Bandwidth: 10MHz

Channel	18650	RB Size 1	RB Offset 0	Channel	18650	RB Size 50	RB Offset 0
---------	-------	-----------	-------------	---------	-------	------------	-------------



Channel Bandwidth: 10MHz

Channel	19150	RB Size 1	RB Offset 49	Channel	19150	RB Size 50	RB Offset 0
---------	-------	-----------	--------------	---------	-------	------------	-------------




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China


Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn

LTE Band 2

Channel Bandwidth: 15MHz



Channel Bandwidth: 15MHz







REPORT No.: SZ18050200W08

LTE Band 2

Channel Bandwidth: 20MHz



Channel Bandwidth: 20MHz



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
[Http://www.morlab.cn](http://www.morlab.cn) E-mail: service@morlab.cn




REPORT No.: SZ18050200W08

LTE Band 4

Channel Bandwidth: 1.4MHz

Channel 19957 RB Size 1 RB Offset 0




Channel 20393 RB Size 6 RB Offset 0



Channel Bandwidth: 1.4MHz

Channel 19957 RB Size 1 RB Offset 5



Channel 20393 RB Size 6 RB Offset 0



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No.: SZ18050200W08

LTE Band 4

Channel Bandwidth: 3MHz

Channel 19965 RB Size 1 RB Offset 0 Channel 20385 RB Size 15 RB Offset 0



Channel Bandwidth: 3MHz

Channel 19965 RB Size 1 RB Offset 14 Channel 20385 RB Size 15 RB Offset 0



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn



REPORT No.: SZ18050200W08

LTE Band 4

Channel Bandwidth: 5MHz

Channel 19975 RB Size 1 RB Offset 0 Channel 20375 RB Size 25 RB Offset 0



Channel Bandwidth: 5MHz

Channel 19975 RB Size 1 RB Offset 24 Channel 20375 RB Size 25 RB Offset 0



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
[Http://www.morlab.cn](http://www.morlab.cn) E-mail: service@morlab.cn




REPORT No.: SZ18050200W08

LTE Band 4


Channel Bandwidth: 10MHz

Channel	20000	RB Size 1	RB Offset 0	Channel	20350	RB Size 50	RB Offset 0
---------	-------	-----------	-------------	---------	-------	------------	-------------



Channel Bandwidth: 10MHz

Channel	20000	RB Size 1	RB Offset 49	Channel	20350	RB Size 50	RB Offset 0
---------	-------	-----------	--------------	---------	-------	------------	-------------



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No.: SZ18050200W08

LTE Band 4


Channel Bandwidth: 15MHz

Channel 20025 RB Size 1 RB Offset 0 Channel 20325 RB Size 75 RB Offset 0



Channel Bandwidth: 15MHz

Channel 20025 RB Size 1 RB Offset 74 Channel 20325 RB Size 75 RB Offset 0



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No.: SZ18050200W08

LTE Band 4


Channel Bandwidth: 20MHz

Channel	20050	RB Size 1	RB Offset 0	Channel	20300	RB Size 100	RB Offset 0
---------	-------	-----------	-------------	---------	-------	-------------	-------------



Channel Bandwidth: 20MHz


Channel	20050	RB Size 1	RB Offset 99	Channel	20300	RB Size 100	RB Offset 0
---------	-------	-----------	--------------	---------	-------	-------------	-------------




MORLAB


SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn














REPORT No.: SZ18050200W08




MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn







REPORT No.: SZ18050200W08



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525
Http://www.morlab.cn E-mail: service@morlab.cn

