







Report No. : EED32K00246406  
Channel Bandwidth: 10 MHz




Page 70 of 340











































Report No. : EED32K00246406  
Channel Bandwidth: 15 MHz




Page 84 of 340




































Report No. : EED32K00246406  
Channel Bandwidth: 20 MHz

Page 98 of 340



