
## **Appendix C. Setup Photographs**


## <Radiated Emission>

X Plane for Cellular Band (DC 12V)

LF




HF




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACC5-HM500 Page Number : C1 of C4
Report Issued Date : Mar. 08, 2016
Report Version : Rev. 01


Report No. : FG611103



X Plane for Cellular Band DC 24V LF




HF




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACC5-HM500 Page Number : C2 of C4
Report Issued Date : Mar. 08, 2016
Report Version : Rev. 01




## Y Plane for PCS Band (DC 12V)

LF



HF




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACC5-HM500 Page Number : C3 of C4
Report Issued Date : Mar. 08, 2016
Report Version : Rev. 01


**Report No. : FG611103** 

## Y Plane for PCS Band (DC 24V)

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACC5-HM500 Page Number : C4 of C4
Report Issued Date : Mar. 08, 2016
Report Version : Rev. 01