



**Appendix A. Test Photos** 

1. Photographs of Conducted Emissions Test Configuration




Report No.: FR611103AL

: A1 of A5

: Rev. 02

**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version

FAX: 886-3-327-0973





Report No.: FR611103AL

**SIDE VIEW** 

 SPORTON INTERNATIONAL INC.
 Page No.
 : A2 of A5

 TEL: 886-3-327-3456
 Report Version
 : Rev. 02

FAX: 886-3-327-0973



FCC Test Report Report No.: FR611103AL

## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A3 of A5 TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973




FCC Test Report No.: FR611103AL

For radiated emissions 30MHz~1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5


Report Version

: Rev. 02




FCC Test Report No.: FR611103AL

## For radiated emissions above 1GHz



## **FRONT VIEW**



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A5

Report Version

: Rev. 02