

Appendix B. Setup Photographs

<Conducted Emission for Model 6055U>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018

Page Number : B1 of B3 Report Issued Date: Aug. 09, 2016 Report Version : Rev. 01

Report No.: FR670106A

Report Template No.: BU5-FR15CBT Version 1.1



<Conducted Emission for Model 6055A>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018

Page Number : B2 of B3 Report Issued Date: Aug. 09, 2016 Report Version : Rev. 01

Report No.: FR670106A


Report Template No.: BU5-FR15CBT Version 1.1




<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : B3 of B3
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR670106A