# Appendix A. Setup Photographs

# <Conducted Emission>

#### Mode 1



Mode 6



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : A1 of A3
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1

Report No. : FC642504


# <Radiated Emission>

# Mode 1

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : A2 of A3
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1

Report No. : FC642504


C Test Report No.: FC642504

# Mode 6

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : A3 of A3
Report Issued Date : May 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1