

Appendix D. Setup Photographs

<Conducted Emission for Model 6055U>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D1 of D4
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report No.: FR670106B

<Conducted Emission for Model 6055A>



Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D2 of D4
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01


Report No.: FR670106B




<Radiated Emission>

Y Plane for Bluetooth v4.0 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D3 of D4
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report No.: FR670106B




Z Plane for Bluetooth v4.2 LE

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D4 of D4
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report No.: FR670106B