


## Appendix D. Test Setup Photos


## **Top Receiver Worked**



**Front View** 



**Left Side View** 



**Right Side View** 

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Page Number : D1 of D1
Report Issued Date : Apr. 06, 2015

**Report No. : HA511301** 

Report Version : Rev. 01




## Report No. : FA511301


## **Bottom Receiver Worked**



**Front View** 



**Left Side View** 



**Right Side View** 

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Report Issued Date: Apr. 06, 2015

Report Version : Rev. 01