Appendix A. Setup Photographs

<Conducted Emission>

Mode 4



Mode 5



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018

Page Number : A1 of A2 Report Issued Date: Aug. 09, 2016 Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC670106


<Radiated Emission>

Mode 6

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : A2 of A2
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

Report No.: FC670106