


## Appendix D. Test Setup Photos


## **Top Receiver Worked**



**Front View** 



Left Side View



**Right Side View** 

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : D1 of D2
Report Issued Date : Apr. 17, 2015

Report No.: HA511301-03


Report Version : Rev. 01




## **Bottom Receiver Worked**



**Front View** 



**Left Side View** 



**Right Side View** 

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : D2 of D2
Report Issued Date : Apr. 17, 2015

Report No.: FA511301-03

Report Version : Rev. 01