
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for LTE Band 2 / 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C1 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5

Report No.: FG611504B

Z Plane for LTE Band 7

LF



HF




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C2 of C4
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5


Report No.: FG611504B

X Plane for LTE Band 13

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C3 of C4

Report Issued Date : Apr. 22, 2016


Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5


Report No.: FG611504B

Z Plane for LTE Band 17

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : C4 of C4

Report Issued Date : Apr. 22, 2016

Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 1.5

Report No. : FG611504B