Appendix A. Setup Photographs

<Conducted Emission> Mode 4




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB003 Page Number : A1 of A3
Report Issued Date : Jan. 27, 2015
Report Version : Rev. 01

Report No.: FC4D0805


<Radiated Emission>

Mode 1

LF



HF




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB003 Page Number : A2 of A3
Report Issued Date : Jan. 27, 2015
Report Version : Rev. 01

Report No.: FC4D0805

Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB003 Page Number : A3 of A3
Report Issued Date : Jan. 27, 2015
Report Version : Rev. 01

Report No.: FC4D0805