

Appendix D. Setup Photographs

<Conducted Emission> Mode 2



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : D1 of D3
Report Issued Date : May 26, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL AC Version 1.4

Report No. : FR611504-04E




Report No. : FR611504-04E


<Radiated Emission>

Z Plane For WLAN 5GHz 802.11a/802.11n HT40

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019

: D2 of D3 Page Number Report Issued Date: May 26, 2016 : Rev. 01 Report Version

Report Template No.: BU5-FR15EWL AC Version 1.4




Report No. : FR611504-04E

Z Plane For WLAN 5GHz 802.11n HT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : D3 of D3
Report Issued Date : May 26, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 1.4