# Appendix A. Setup Photographs

# <Conducted Emission>

#### Mode 3



Mode 4




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB051 Page Number : A1 of A5
Report Issued Date : Feb. 29, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1

Report No. : FC612204

#### Mode 5



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB051 Page Number : A2 of A5
Report Issued Date : Feb. 29, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1

Report No. : FC612204

# <Radiated Emission>

# Mode 2

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB051 Page Number : A3 of A5
Report Issued Date : Feb. 29, 2016
Report Version : Rev. 01

Report No.: FC612204

Report Template No.: BU5-FC15B Version 1.1

# Mode 4

LF



# HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB051 Page Number : A4 of A5
Report Issued Date : Feb. 29, 2016
Report Version : Rev. 01

Report No.: FC612204

Report Template No.: BU5-FC15B Version 1.1

# Mode 5

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB051 Page Number : A5 of A5
Report Issued Date : Feb. 29, 2016
Report Version : Rev. 01

Report No.: FC612204

Report Template No.: BU5-FC15B Version 1.1