
Appendix D. SAR Test Setup Photos

Without Holster

<Receiver 1>:






Report No.: FA642504

Right Cheek








Left Cheek

Left Tilted

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958


Issued Date: May 28, 2016 Form version. : 151208 FCC ID: 2ACCJA015 Page D1 of D4



Front, Test Separation 10 mm

Back, Test Separation 10 mm


Report No.: FA642504




Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm




Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

TEL: 86-755-8637-9589/ FAX: 86-755-8637-9595

Issued Date: May 28, 2016 Form version. : 151208 FCC ID: 2ACCJA018 Page D2 of D4



Front, Test Separation 15 mm

Back, Test Separation 15 mm

Report No.: FA642504

With Holster

<Receiver 1>:








Report No.: FA642504

Right Cheek


Left Cheek








Back, Test Separation 15 mm



Back, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

TEL: 86-755-8637-9589/ FAX: 86-755-8637-9595

Issued Date: May 28, 2016 Form version. : 151208 FCC ID: 2ACCJA018 Page D4 of D4