

Appendix C. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : C1 of C3
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.2

Report No.: FR652006B







<Radiated Emission>

Y Plane for BLE v4.0

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : C2 of C3
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.2


Report No.: FR652006B






Z Plane for BLE v4.2

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : C3 of C3
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.2

Report No.: FR652006B