

7/F, Block F4, TCL Communication Technology Building, TCL International E City, Zhong Shan Yuan Road, Nanshan District, Shenzhen, Guangdong, P.R. China 518052 TEL: 0086-755-36611722

Declaration of changes from 5002S to 5002L

• SOFTWARE MODIFICATIONS:

Protocol Stack changes: NO

MMS/STK/USAT/USIM changes: NODM/SUPL/VT/FUMO/SWP/HCI: NO

> Other changes detailed: code name changed, and software version will be changed.

• HARDWARE MODIFICATIONS:

Band changes: NO

PCB Layout changes: NOMain components changes:

	Antenn	Base	Transceive	ASM	Power	Tx	Rx	Duplex
	а	Band	r		Amplifier	SAW	SAW	er
					-	Filter	Filter	
GSM850	NO	NO	NO	NO	NO	NO	NO	NO
GSM900	NO	NO	NO	NO	NO	NO	NO	NO
GSM1800	NO	NO	NO	NO	NO	NO	NO	NO
GSM1900	NO	NO	NO	NO	NO	NO	NO	NO
UMTS2100	NO	NO	NO	NO	NO	NO	NO	NO
UMTS1900	NO	NO	NO	NO	NO	NO	NO	NO
UMTS1700	NO	NO	NO	NO	NO	NO	NO	NO
UMTS900	NO	NO	NO	NO	NO	NO	NO	NO
UMTS850	NO	NO	NO	NO	NO	NO	NO	NO
LTE 2	NO	NO	NO	NO	NO	NO	NO	NO
LTE 4	NO	NO	NO	NO	NO	NO	NO	NO
LTE 5	NO	NO	NO	NO	NO	NO	NO	NO
LTE 7	NO	NO	NO	NO	NO	NO	NO	NO
LTE 12	NO	NO	NO	NO	NO	NO	NO	NO
LTE 13	NO	NO	NO	NO	NO	NO	NO	NO
LTE 17	NO	NO	NO	NO	NO	NO	NO	NO
LTE 66	NO	NO	NO	NO	NO	NO	NO	NO
Bluetooth	NO	NO	NO	NO	NO	NO	NO	NO
WiFi	NO	NO	NO	NO	NO	NO	NO	NO

➤ FM changes: NO

Other components changes:
LCD/ Speaker/ Vibrator change

LCD/ Speaker/ Vibrator changes: NO

Other changes detailed:NO

MECHANICAL MODIFICATIONS:

Use new metal front/back cover or keypad: No

Mechanical shell changes: Whole size of EUT: No Distance of Ear reference point to bottom of handset: No
Other trinkets to change the surface of handset: No
Other changes detailed:

APPROVED BY:

Project Manager: 史睿

Signature:

Date: 2019-11-29