

## Appendix D. Setup Photographs

## <Conducted Emission for Model 6055U> Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D1 of D5
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC Version 1.2

Report No.: FR670106F



Report No. : FR670106F






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D2 of D5
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01




## <Radiated Emission>

## Z Plane For WLAN 5GHz 802.11n HT40/802.11ac VHT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D3 of D5
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report No.: FR670106F




Y Plane For WLAN 5GHz 802.11ac VHT80

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D4 of D5
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report No.: FR670106F






Z Plane For WLAN 5GHz 802.11a/802.11n HT20/802.11ac VHT40 LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D5 of D5
Report Issued Date : Aug. 09, 2016
Report Version : Rev. 01

Report No.: FR670106F