

Report No.: FR511301-29E

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : C1 of C3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01




Report No.: FR511301-29E


<Radiated Emission>

Y Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : C2 of C3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01






Report No. : FR511301-29E


<Radiated Emission for Spot Check>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : C3 of C3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01