

## Appendix A. Setup Photographs

## <Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Page Number : A1 of A2
Report Issued Date : Apr. 06, 2015
Report Version : Rev. 01


Report No.: FR511301D




Report No.: FR511301D

## <Radiated Emission>

## Y Plane



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Page Number : A2 of A2
Report Issued Date : Apr. 06, 2015
Report Version : Rev. 01