# Appendix A. Setup Photographs

# <Conducted Emission> Mode 4




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB023 Page Number : A1 of A3
Report Issued Date : Jul. 06, 2015
Report Version : Rev. 01

Report No.: FC4D0805-02


## <Radiated Emission>

#### Mode 1

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB023 Page Number : A2 of A3
Report Issued Date : Jul. 06, 2015
Report Version : Rev. 01

Report No. : FC4D0805-02

C Test Report No. : FC4D0805-02

### Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB023 Page Number : A3 of A3
Report Issued Date : Jul. 06, 2015
Report Version : Rev. 01