Appendix A. Setup Photographs

<Conducted Emission>

Mode 3



Mode 6



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : A1 of A3
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC5D1401


<Radiated Emission>

Mode 2

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : A2 of A3
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No.: FC5D1401

Mode 5

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : A3 of A3
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC5D1401