

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : C1 of C2
Report Issued Date : Aug. 27, 2015
Report Version : Rev. 01

Report No.: FR511301-21F




Report No.: FR511301-21F


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005

: C2 of C2 Page Number Report Issued Date : Aug. 27, 2015 Report Version : Rev. 01