

Appendix C. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : C1 of C4
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2






<Radiated Emission>

Z Plane for WLAN 802.11b

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : C2 of C4
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2






Y Plane for WLAN 802.11g

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : C3 of C4
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2






X Plane for WLAN 802.11n HT20

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : C4 of C4
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 1.2