

_ . . . _ . .

Appendix D. Setup Photographs



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D1 of D2
Report Issued Date : May 27, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0

Report No.: FR642504D




<Radiated Emission>



Report No.: FR642504D

From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA018 Page Number : D2 of D2
Report Issued Date : May 27, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CNFC Version 1.0