

# Appendix D. Setup Photographs

# <Conducted Emission>

#### Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : D1 of D2
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL AC Version 1.3

Report No.: FR652006F







## <Radiated Emission>

### **Z** Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : D2 of D2
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL AC Version 1.3

Report No.: FR652006F