

Report No.: FR511301-29C

# Appendix C. Setup Photographs

## <Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : C1 of C3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01




### Report No. : FR511301-29C

#### <Radiated Emission>

#### Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : C2 of C3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01




# <Radiated Emission for Spot Check>

Y Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : C3 of C3
Report Issued Date : Mar. 07, 2016

Report No.: FR511301-29C

Report Version : Rev. 01