

Appendix A. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : A1 of A2
Report Issued Date : Mar. 07, 2015
Report Version : Rev. 01


Report No.: FR511301-29D




Report No.: FR511301-29D

<Radiated Emission>

Y Plane



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005

Page Number : A2 of A2 Report Issued Date: Mar. 07, 2015

Report Version : Rev. 01



<Radiated Emission for Spot Check>

Z Plane



From 9kHz~30MHz



From 30MHz~1GHz

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : A3 of A2 Report Issued Date : Mar. 07, 2015 Report Version : Rev. 01

Report No.: FR511301-29D