

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1





SPORTON International (ShenZhen) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJBT01 Page Number : A1 of A3
Report Issued Date : Mar. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1

Report No. : FC711703



Mode 4





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJBT01 Page Number : A2 of A3
Report Issued Date : Mar. 24, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No. : FC711703

<Radiated Emission>

Mode 4

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJBT01 Page Number : A3 of A3
Report Issued Date : Mar. 24, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1

Report No. : FC711703