


Appendix D. Test Setup Photos


Top Receiver Worked



Front View



Left Side View



Right Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Page Number : D1 of D2
Report Issued Date : Apr. 10, 2015

Report No. : HA511301


Report Version : Rev. 02




Bottom Receiver Worked



Front View



Left Side View



Right Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Page Number : D2 of D2 Report Issued Date : Apr. 10, 2015

Report No. : FA511301

Report Version : Rev. 02