

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : B1 of B3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01


Report No.: FR511301-29B



<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : B2 of B3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01


Report No. : FR511301-29B




<Radiated Emission for Spot Check>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : B3 of B3 Report Issued Date : Mar. 07, 2016

Report No.: FR511301-29B

Report Version : Rev. 01