
3. Internal Photograph of EUT

Brand Name: BlackBerry / Model Name: BBA100-1 / Marketing Name: DTEK60


Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 17 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01




Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 18 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01



Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 19 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01



Brand Name: BlackBerry / Model Name: BBA100-1 / Marketing Name: DTEK60

OF 02 08 04 08 08 07 08 08 00 00 02 02 02 03 07 08 C8 00

0 02 06 07 09 02 08 00 101 02 06 07 09 02 08 06 00 02 08 07 08 06 00 07 08 07 08 07 08 07 08 07 08 07 08 07 08


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 20 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01

Report No.: EP672002



Brand Name: BlackBerry / Model Name: BBA100-1 / Marketing Name: DTEK60




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001

Page Number : 21 of 40 Report Issued Date : Aug. 23, 2016 Report Version : Rev. 01



Report No.: EP672002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001

Page Number : 22 of 40 Report Issued Date : Aug. 23, 2016 Report Version : Rev. 01




Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 23 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01




Brand Name: BlackBerry / Model Name: BBA100-1 / Marketing Name: DTEK60



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 24 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01




Brand Name: BlackBerry / Model Name: BBA100-1 / Marketing Name: DTEK60



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 25 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01




Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 26 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01



Brand Name: BlackBerry / Model Name: BBA100-1 / Marketing Name: DTEK60




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001

Page Number : 27 of 40 Report Issued Date : Aug. 23, 2016 Report Version : Rev. 01



Brand Name: BlackBerry / Model Name: BBA100-1 / Marketing Name: DTEK60



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001

Page Number : 28 of 40 Report Issued Date : Aug. 23, 2016 Report Version : Rev. 01


Report No.: EP672002



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 29 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01


Report No.: EP672002



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 30 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01

Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 31 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01

Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 32 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01


Report No.: EP672002



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 33 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01

Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 34 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01

Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 35 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01

Report No.: EP672002




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 36 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01



Report No.: EP672002




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001

Page Number : 37 of 40 Report Issued Date : Aug. 23, 2016 Report Version : Rev. 01




Report No.: EP672002



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 38 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 39 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01

Report No.: EP672002



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: L6ABBA1001 Page Number : 40 of 40
Report Issued Date : Aug. 23, 2016
Report Version : Rev. 01