

Appendix C. Setup Photographs

<Conducted Emission> Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : C1 of C2
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01


Report No.: FR5D1401E

Report Template No.: BU5-FR15EWL AC Version 1.3


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN007 Page Number : C2 of C2
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15EWLAC Version 1.3

Report No.: FR5D1401E