Appendix A. Setup Photographs

<Conducted Emission>

Mode 4



Mode 6



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : A1 of A3
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No. : FC611504


<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : A2 of A3
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No. : FC611504


C Test Report No. : FC611504

Mode 6

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : A3 of A3
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1