
Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB052 Page Number : A1 of A3
Report Issued Date : Feb. 29, 2016
Report Version : Rev. 01


Report Template No.: BU5-FD15B Version 1.0

Report No. : FC612205

<Radiated Emission>

Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB052 Page Number : A2 of A3
Report Issued Date : Feb. 29, 2016
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.0

Report No.: FC612205


C Test Report No.: FC612205

Mode 5

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB052 Page Number : A3 of A3
Report Issued Date : Feb. 29, 2016
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.0